

# ASSISTANCE SHEET

DATE

26/03/2018

Зип Общепит

vsezip.ru

+7(812)987-08-81

## GENERAL INFORMATION

Assistance sheet code	SA84
Title description	Instruction replacement EXPLORA motor



**SAFETY WARNING!** The indications in this service file must be only performed by authorized technical service.  
Any intervention done by non-authorized personal will invalidate the one-year factory warranty.  
Piron is not liable for any damage caused to the equipment or any physical injuries occurring from actions performed not in accordance with the above indications.

**PIRON**<sup>®</sup>  
your professional cooking

# ASSISTANCE SHEET

DATE

26/03/2018

Зип Общепит


vsezip.ru

+7(812)987-08-81

## To do 1:



Disconnect the oven from the power grid.



REMOVE  
THE  
MOTOR'S  
COVER (IN  
RED)  
INSIDE THE  
CAVITY



SAFETY WARNING! The indications in this service file must be only performed by authorized technical service. Any intervention done by non-authorized personal will invalidate the one-year factory warranty. Piron is not liable for any damage caused to the equipment or any physical injuries occurring from actions performed not in accordance with the above indications.

**PIRON**<sup>®</sup>  
your professional cooking

# ASSISTANCE SHEET

Вип Общежит


DATE

26/03/2018

vsezip.ru

+7(812)987-08-81

REMOVE  
THE  
IMPELLER  
(IN RED)  
INSIDE THE  
CAVITY



**SAFETY WARNING!** The indications in this service file must be only performed by authorized technical service. Any intervention done by non-authorized personal will invalidate the one-year factory warranty. Piron is not liable for any damage caused to the equipment or any physical injuries occurring from actions performed not in accordance with the above indications.

**PIRON**<sup>®</sup>  
your professional cooking

# ASSISTANCE SHEET

Зип Общепит

DATE

26/03/2018

vsezip.ru

+7(812)987-08-81



REMOVE  
THE BACK  
OF THE  
OVEN



SAFETY WARNING! The indications in this service file must be only performed by authorized technical service.  
Any intervention done by non-authorized personal will invalidate the one-year factory warranty.  
Piron is not liable for any damage caused to the equipment or any physical injuries occurring from actions performed not in accordance with the above indications.

**PIRON**<sup>®</sup>  
your professional cooking

# ASSISTANCE SHEET

DATE


26/03/2018

Випл. Общепит

vsezip.ru

+7(812)987-08-81

UNSCREW THE  
SENSOR  
MOTOR'S  
,UNSCREWS  
THE 4 SCREWS  
AND PULL OUT  
THE MOTOR .  
CHANGE IT  
AND FIX THE  
SENSOR ON  
THE NEW  
MOTOR.FIX  
THE MOTOR.



Reconnect the oven to the power grid